




Ergonomic Workstations

## **Social Distancing Dividers**




Tool List			
1/2" wrench			
Ratchet with 1/2" socket, or impact driver with 1/2" socket			


Part # WPS3672 - Work Partition 72"h x 26"d x 36"w, WPS4872 - Work Partition 72"h x 26"d x 36"w

Item	Components	Qty
Α	Panel frame assembly	1
В	Leg support	2
С	Top tie plate	1
D	Leveler feet	4
Е	5/16-18 x 1" hex head cap screw	6
F	5/16" flat washer	8
G	5/16" lock washer	10
Н	5/16-18 hex nut	10

<sup>\*</sup>Addtional hardware supplied for joining frames side by side

Attach leveler feet (D) to leg support (B) (Fig-1a). Replace leveler feet with casters for extra mobility (Fig-1b). Attach leg support (B) to the panel frame assembly (A) using a 5/16-18 x 1" hex head cap screw (E), 5/16" flat washers (F), 5/16" lock washers (G), and 5/16-18 hex nuts (H).





bostontec.com

989.496.9510



## **Social Distancing Dividers**

Join two frames side by side:

Place two frames together with two leg supports pressed against each other. Use  $5/16-18 \times 1$ " hex head cap screws (E), 5/16" flat washers (F), 5/16" lock washers (G), and 5/16-18 hex nuts (H) to connect two leg supports at front and back (Fig-2a). Use a top tie plate (C),  $5/16-18 \times 1$ " hex head cap screws (E), 5/16" flat washers (F), 5/16" lock washers (G), and 5/16-18 hex nuts (H) to connect the frames at the top (Fig-2b).




Fig-2b






Ergonomic Workstations

## **Social Distancing Dividers**

## Join two frames at corners:

Remove one leg from a frame and place it at a 90-degree angle with another frame. Use a corner joining bracket (I),  $5/16-18 \times 1$ " hex head cap screws (E), 5/16" flat washers (F), 5/16" lock washers (G), and 5/16-18 hex nuts (H) to join the two frames at the bottom (Fig-3a). Use the top tie plate (C),  $5/16-18 \times 1$ " hex head cap screws (E), 5/16" flat washers (F), 5/16" lock washers (G), and 5/16-18 hex nuts (H) to join two frames at the top (Fig-3b).



Item	Components	Qty
1	Corner joining bracket	1
E	5/16-18 x 1" hex head cap screw	2
F	5/16" flat washer	2
G	5/16" lock washer	2
Н	5/16-18 hex nut	2

Part # WPSCJK - Corner Joining Kit

\*Additional hardware supplied with the frames will be used in corner assembly.




Fig-3b